

MANDATORY SERVICE BULLETINES										W:O		CAT		ALERT - MANDATORY		ASB - 1		RECOMMENDED		OPTIONAL	
A/C REG:		ENG.SN:		EASA TCDS		Page		of		CODE		PRE COMPLIED WITH		PCW		PARTIALLY PERFORMED		CANCELLED			
SE-JML		CAE-836554		IM.E.052		"ESB " ROLLS ROYCE 250-C20J		Bi-Weekly		2017-10 EASA		NOT PERFORMED		PERFORMED		NOT APPLICABLE		N			
MO	sb	CEB	rev	FAA-AD	EASA AD	ACTION	PART	REP	DUE	CAT	REMARK	CODE	MTD. OF COMPLIANCE	WO NC	DATE	INSP					
FC		INB1005	4			ADD ACCUMULATOR FOR BENDIX SYSTEM	1		1	2		PCW	P.C.W ON ENGINE		10-7 2003	A&P2519879					
EG		INB1004	5			ACCUMULATOR & CHECK VALVE. BENDIX SYSTEM	1		1	2	NEXT OH-REP-INSP	X	C.W INSP	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD					
TU		DIL-139				PRESS TEST DISCHARGE AIR TUBE	1		1	2	NEXT OH-REP-INSP		C.W ON TU SN CAT-37612								
TU		DIL-123				REPLACE SPLITLINE BOLTS	1		1	2	NEXT OH-REP-INSP		C.W ON TU SN CAT-37612								
FC		CSL-A-1166	*		2004-0009R3	TORQUE LOAD ON "B" NUTS	1		1	ASB	NEXT OH-REP-INSP	X	C.W INSP INCORP IN ESL & MP CHAP 4.1	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD					
TU		CSL-1060	3			TURBINE NUT INSP	1		1	ASB	500 HRS INSP	NA	NA DUE TO TURBINE MOD STATUS	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD					
FC		CSL-1023		74-14-03	*	CECO FUEL CONTROL MC-40	1		1	ASB	PN 6875653,-	NA	NA BENDIX INSTALLED		1-12 2003	A&P2519879					
EG		CSL-1005	13			TIME LIMETED PARTS	1	300	1	ASB		X	C.W. NEXT DUE 2018-05-22	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD					
EG		CSL-1004	20			TIME BETWEEN OVERHAUL	1	300	1	ASB		X	C.W. NEXT DUE 2018-05-22	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD					
TU	A	1421				TURBINE ASSEMBLY - NO.8 BEARING MFG BY NHBB	I		1750	ASB	NEXT OH-HMI-REP	NA	C.W ON TU SN CAT-37612	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD					
TU	A	1418	1			TURBINE ASSEMBLY - INSP. OF 3RD STAGE TURBINE WHEELS 23065818	I		1750	ASB	NEXT OH-REP-INSP	NA	C.W INSP CHECK 2 ND PERIOD	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD					
TU		1417				TURBINE- NO.5 BEARING RETAINING RING REPLACEMENT	I			6	NEXT OH-HMI-REP										
CO	A	1416				ENGINE COMPRESSOR ASSEMBLY-INSP. OF FRONT SUPPORT PN: M250-10051-10052-10059- 10060	I		1750	ASB	NEXT OH-REP-INSP	NA	NA DUE TO PN INSTALLED IS 6890530	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD					
TU		1414	1			TURBINE - N2 SHAFT REPLACEMENT	I		1	2	NEXT OH-REP-INSP		C.W ON TURBINE SN CAT-37612								
FC		1413	1			PTG - PTG DRIVE BEARING REPLACEMENT PN: 2543734	I		1	2	REPLACE HW BRG. PN 2543734	X	C.W. BEARING EXCH. INCORP IN ESL FOR FOLLOW UP	ESP 16862	29-2 2016	ESP SE.145.0134					
FC		1412	2			FCU - HONEYWELL MAIN FCU - REPLACEMENT OF THE BYPASS VALVE SLEEVE	I		1	2	HW SB: GT-73-362	NA	NA DUE TO PN ON FCU PN 323207	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD					
FC		1411	1			FUEL NOZZLE - SPRAY TIP/INNER AIR SHROUD EPLACEMENT	I		1	6											
EG		1408				ENGINE CONVERSION, M250--C20B TO M250--C20W	I		1	7		NA	NA AT THIS TIME								
TU		1407	4	2015-02-22	*	TURBINE ASSEMBLY -3RD PN 23065818 AND 4TH STAGE WHEEL PN 23055944 ENHANCED POWER TURBINE WHEEL	I		1	ASB	1750 HMI INSP	NA	NA TURBINE SN: CAT-37612 DUE TO WHEEL PN INSTL.	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD					
TU		1406	1			TURBINE ASSEMBLY - REPLACEMENT OF TURBINE GAS PRODUCER FORWARD LABYRINTH SEAL. NEW PN 23089424	I		1	5		X	C.W ON TU SN CAT-37612		13-6 2006	H+S 2590					
FC		1405				FCU- HONEYWELL - REPL. OF CUTOFF VALVE LEVER AND SHAFT ASSY, AND DRIVE BODY ASSY	I		1	2	HW-PN: 2524654--27		NA ON FCU SN: 323207, DUE TO PN INSTL.								
FC		1404				FCU- HONEYWELL MAIN FUEL CONTROLS - VERIFICATION OF FUEL FLOW CALIBRATION	I		1	1	BENDIX SYSTEM	NA	NA ON FCU SN: 323207 DUE TO SN INSTL.	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD					
PT		1402	1			PTG - INCREASED REABILITY DESIGN WITH NEW BEARING ASSEMBLY,	I		1	2	HONEYWELL PN 23076418, 23076061 SB; GT-73-344		C.W								

MANDATORY SERVICE BULLETINES						W:O	CAT		ALERT - MANDATORY		ASB - 1		RECOMMENDED		2		OPTIONAL		3	
A/C REG:		ENG.SN:		EASA TCDS		Page		of		CODE		PRE COMPLIED WITH		PCW		PARTIALLY PERFORMED		CANCELLED		
SE-JML		CAE-836554		IM.E.052		"ESB " ROLLS ROYCE 250-C20J		Bi-Weekly		2017-10 EASA		NOT PERFORMED		PERFORMED		NOT APPLICABLE		N		
MO	sb	CEB	rev	FAA-AD	EASA AD	ACTION	PART	REP	DUE	CAT	REMARK	CODE	MTD. OF COMPLIANCE		WO NC	DATE	INSP			
TU	A	1400	3	*	2009-0022-E	TURBINE ASSEMBLY - STEADY STATE OPERATION AVOIDANCE RANGE LIMIT TO 60 SEC. INSIDE RANGE N1 RPM 75-88%	I		1	1	WITH 3RD WHEEL PN 23065833, AND 23065818	NA	NA ON TURBINE SN CAT-37612, DUE TO WHEEL PN INSTALLED IS 23001967		HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD			
TU		1399	1			TURBINE - INSP SUMP ASSY	I, II		1	2	NEXT OH-HMI-REP	X	C.W ON TU SN CAT-37612			13-6 2006	H+S 2590			
TU	A	1398	3			TURBINE ASSEMBLY - POWER TURBINE OUTER SHAFT	I		1	1	NEXT OH-HMI-REP	X	C.W ON TU SN CAT-37612			28-3 2007	ES PARTNERS AB ESP-2			
GB		1395				GEARBOX - REPLACE OF BREATHER SEAL	I		1	7			C.W ON GEARBOX SN: CAG-37519							
FC	A	1394	1	2006-16-14	*	ENGINE - FUEL DELIVERY - RELEASE OF NEW FUEL NOZZLE	I		1	ASB		X	C.W ON NOZZLE SN AG16457			5-10 2005	ESP08			
CO	A	1392		2004-26-09	*	COMPRESSOR ADAPTER COUPLING - REPLACE CERTAIN PNs	I		1	ASB	RRC Adaptors NEXT OH-REP, Others 650Hrs	X	C.W ON COMP SN CAC-35224			22-2 2008	HH. NL.145.1157			
PT		1391				PTG INCREASED DURABILITY DESIGN	1		1	7	NEW TYPE PTG		OPTIONAL							
EG		1389				COMP - FRONT BEARING HOUSING	1		1	1		X	C.W ON COMP SN CAC-35224			22-2 2008	HH. NL.145.1157			
EG		1388				MAIN GEARBOX - RELEASE OF REWORK AND REIDENTIFIED LIP SEALS	1		1	7	NEW SEAL TYPE		C.W AT SEAL CHANGES							
TU	A	1387				TURBINE- REPLACEMENT OF 3RD STAGE WHEEL	1		1	ASB	250-C20W NEXT OH-REP- INSP	NA	NA DUE TO ENGINE MODEL		HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD			
GB	A	1386	1	2001-24-12		GEARBOX - HELICAL TORQUEMETER GEARSHAFT FAILURE	1		1	ASB	HTG WITH LESS THEN 100HRS TSN	PCW	NA DUE TO HRS OF OPERATION, ON GB SN27441			10-1 2002	SAPB 553534452			
EG		1385	1			ENGINE, CONTROL SYSTEM - ONE TIME INSPECTION	1		1	1	MD HCPS	NA	NA DUE TO ENGINE INSTALLATION IN BELL		HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD			
FC		1384				FCU- HONEYWELL/BENDIX/ALLIED SIGNAL; PTG - TEE FILTER INSPECTION	1		1	1	BEFORE 4-1-03, OR WITHIN 2000 HRS	NA	NA ON PTG SN 25950 DUE TO SN INSTALLED		HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD			
FC		1382	1			FCU- ONE TIME INSPECTION OF SCREWS	1		1	5	NEXT OH-REP		C.W ON FCU SN 323207							
EG		1379				GEARBOX - CONVERSION OF C20R AUTO RELIGHT KIT TO - C20B/J	1		1	3			C.W ON RELIGHT SYSTEM							
TU	A	1375	3			TURBINE- REPLACEMENT OF 2ND STAGE NOZZLE DIAPHRAM	1		1	ASB	NEXT HMI-OH INCORP ESL FOLLOW UP 3500 HRS OH	X	C.W ON TU SN CAT-37612			13-6 2006	H+S 2590			
CO	A	1374	1			COMPRESSOR ASSY- VISUAL INSP. OF COMPRESSOR SCROLL PRESSURE PROBE ELBOW	1		1	ASB	NEXT OH-REP	X	NA BY PN ON CO SN CAC-35224			22-2 2008	HH. NL.145.1157			
TU		1373				TURBINE-ONE-TIME INSP. FOR OVERTEMPERATURE DAMAGE	1		1	3	NEXT OH-REP		C.W ON TU SN CAT-37612							
GB	A	1372				GEARBOX- INSP. FOR INSTL. OF TORQUEMETER RETAINING RING	1		1	3	NEXT OH-REP	X	C.W ON GEARBOX SN: CAG-37519			9-11 2001	SAL-AMO-22-58			
TU		1371	3	2006-13-06		TURBINE ASSEMBLY- GAS PRODUCER ROTOR ASSEMBLY-REPLACE TURBINE TIE BOLT	I		1	ASB	NEXT OH-HMI-REP	X	C.W ON TU SN CAT-37612			2001-05-26	HELI-PLAN			
TU	A	1370	8			TURBINE- INSP. OF 1ST STAGE NOZZLE STAGE DOME, PN 6890040	1		1	ASB	1000 CYCLES	X	C.W ON TU SN CAT-37612 INCORP IN ESL			13-6 2006	H+S 2590			
CO		1369				COMPRESSOR ASSEMBLY- IMPELLER REWORK	1		1	2	NEXT OH-REP		C.W ON CO SN CAC-35224							
FC		1367				FCU- RELEASE OF NEW BYPASS RETENTION PLATE	1		1	3	NEXT OH-REP		C.W							

MANDATORY SERVICE BULLETINES						W:O		CAT			ALERT - MANDATORY			ASB - 1		RECOMMENDED		2		OPTIONAL		3	
A/C REG:		ENG.SN:		EASA TCDS		Page		of		CODE		PRE COMPLIED WITH		PCW		PARTIALLY PERFORMED		CANCELLED		NOT APPLIED		N	
SE-JML		CAE-836554		IM.E.052		"ESB " ROLLS ROYCE 250-C20J						Bi-Weekly		2017-10		EASA		NOT PERFORMED		PERFORMED		NOT APPLICABLE	
MO	sb	CEB	rev	FAA-AD	EASA AD	ACTION	PART	REP	DUE	CAT	REMARK	CODE	MTD. OF COMPLIANCE		WO NC	DATE	INSP						
FC		1366				FC- HONEYWELL MODEL DP-N2 FCU - INSP AND REPLACEMENT OF CONTROL THROTTLE LEVER	1		1	6	NEXT OH-REP		C.W ON FCU SN 323207										
TU		1365	1			TURBINE - P.T WITH IMPROVED AIRFLOW CHARACTERISTICS	1		1	2	NEXT OH-REP		P.C.W ON TU SN CAT-37612										
GB		1363				GEARBOX - RELEASE OF NEW HELICAL TORQUEMETER	1		1	2	NEXT OH-REP		C.W ON GEARBOX SN: CAG-37519										
FC		1362				CECO MC-40; FCU, GOV REPLACEMENT OF MUSCLES VALVE LOCKNUT	1		1	2	CECO SYSTEM	NA	NA DUE TO INSTL.. SYSTEM		HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD						
FC	A	1361	3			FCU - GOVERNOR- ALLIED SIGNAL -BENDIX- INTERNAL SPRING REPLACEMENT	1		1	ASB		X	C.W			29-6 1999	DALLAS AIRM. YRRR4191L						
TU		1360	1			TURBINE - RECOATING OF INNER POWER TURBINE SHAFT	1		1	6	NEXT OH-REP	X	C.W ON TU SN CAT-37612			28-3 2007	ES PARTNERS AB ESP-2						
FC		1357				FCU- INCORP. ONE PIECE BYPASS VALVE SLEEVE	1		1	2	NEXT OH-REP	X	C.W			29-6 1999	DALLAS AIRM. YRRR4191L						
EL		1354				ELECTRICAL - START COUNTER ASSY - REMOVAL / INSTALLATION	1		1	2	NEXT OH-REP		C.W										
FC	A	1353	2			FCU - GOVENOR - INSP. CAM FOLLOWER LEVER	1		1	ASB	100 HRS INSP/ REMOV	X	C.W			29-6 1999	DALLAS AIRM. YRRR4191L						
FC	A	1352				FUEL PUMP- CECO -INTERNAL SPLINE INSPECTION	1		1	ASB	CECO FCU INSTL	NA	NA TO THIS INSTL BENDIX			1-12 2003	A&P2519879						
GB	A	1351	1			GEARBOX - OIL DELIVERY TUBE-REPLACE	1		1	1	ALL ENGINES BUILT BEFORE 1.1.93	X	C.W ON GEARBOX SN: CAG-37519			29-6 1999	DALLAS AIRM. YRRR4191L						
EG	A	1349				VISUAL INSP OF TURBINE LUBE OIL CLAMP TYPE PN 23062081	1		1	ASB	AES-MFC FCU	NA	NA DUE TO CHECK VALVE INSTALLED			28-1 2004	A&P2519879						
FC		1348	2			FCU - GOVERNOR -L, FCU STOP NUT -REWORK	1		1	2	NEXT FCU REP/OH	X	C.W			29-6 1999	DALLAS AIRM. YRRR4191L						
FC		1347				FCU - GOVERNOR, PTG DRIVE BEARINGS	1		1	2	NEXT FCU/ PTG OH	X	C.W			29-6 1999	DALLAS AIRM. YRRR4191L						
FC		1345	2			FCU - GOVERNOR - BENDIX L- FCU DRIVE BEARINGS-REPLACE	1		1	2	AES-MFC FCU	X	C.W			29-6 1999	DALLAS AIRM. YRRR4191L						
TU	A	1342	2			TURBINE - INSP. OF FIRST STAGE NOZZLE SHIELD DOME DETAIL FOR HMI OR OVERHAUL	1		1	ASB	NEXT TURBINE OH/REP	X	C.W ON TU SN CAT-37612			10-6 2003	ALCA AEROSPACE 231-01 SCA T.11						
TU	A	1341	2			TURBINE - VISUAL INSP. OF CERTAIN FIRST STAGE NOZZLE SHIELD DOME DETAILS FOR CONDITION	1		1	ASB	NEXT TURBINE OH/REP	NA	NA DUE TO SN INSTALLED IN CAT-37612			10-6 2003	AEROSPACE 231-01 SCA T.11						
GB	A	1340	1			GEARBOX - REMOVAL OF CERTAIN PINION GEARS	1		1	ASB	C20B-J-W-R/1	X	C.W ON GEARBOX SN: CAG-37519			7-7 1997	PHI R.S. HEER617E						
FC		1338				CECO FUEL CONTROL MC-40	1		1	2	NEXT FCU OH		NA DUE TO INSTL.. SYSTEM										
FC	A	1336				FCU - MAXIMUM FCU FLOW SETTING ADJUSTMENT	1		1	ASB	C20C	NA	NA DUE TO ENGINE MODEL			1-12 2003	A&P2519879						
TU		1333	3			TURBINE ASSY, 2ND STAGE NOZZLE	1		1	2	NEXT OH-REP		C.W ON TU SN CAT-37612										
FC		1331	2			GOVERNOR - AES - SHAFT ASSY MOD	1		1	3	NEXT OH-REP		C.W										
FC		1330	4			FCU - GOVERNOR - BENDIX - MOD	1		1	3	OH, NEW PY TUBE	X	C.W			29-6 1999	DALLAS AIRM. YRRR4191L						

MANDATORY SERVICE BULLETINES						W:O	CAT		ALERT - MANDATORY		ASB - 1		RECOMMENDED		2		OPTIONAL		3	
A/C REG:		ENG.SN:		EASA TCDS		Page		of		CODE		PCW		PARTIALLY PERFORMED		CANCELLED				
SE-JML		CAE-836554		IM.E.052		"ESB " ROLLS ROYCE 250-C20J		Bi-Weekly		2017-10 EASA		NOT PERFORMED		PERFORMED		NOT APPLICABLE		N		
MO	sb	CEB	rev	FAA-AD	EASA AD	ACTION	PART	REP	DUE	CAT	REMARK	CODE	MTD. OF COMPLIANCE		WO NC	DATE	INSP			
FC	A	1329	4	98-24-28		FCU - FCU BELLOWS - REPLACE	1		1	ASB		PCW	P.C.W ON FCU SN 323207			1-12 2003	A&P2519879			
CO	A	1328				COMPRESSOR ASSEMBLY- SPUR ADAPTER GEARSHAFT ASSY PN 23034784, INSP	1		1	ASB		NA	NA DUE TO SHAFT PN C.W ON CO SN CAC-35224		HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD			
TU		1327				TURBINE - 2ND STAGE NOZZLE	1		1	2	NEXT OH-REP		C.W ON TU SN CAT-37612							
TU		1326				TURBINE - RELEASE OF NEW NO. 8 BRG AND RETAINING PLATE	1		1	2	NEXT OH-REP	X	C.W ON TU SN CAT-37612			28-3 2007	ES PARTNERS AB ESP-2			
CO		1325	2			COMPRESSOR - COUPLING ADAPTER	1		1	2	NEXT COMP. OH		C.W ON CO SN CAC-35224							
TU		1324				TURBINE - RELEASE OF NEW HORIZONTAL FIRESHIELD AND ACCESS PANEL - REWORK	1		1	2	NEXT OH-REP		C.W ON TU SN CAT-37612							
FC	A	1323	3			FCU AND CONTROL - REPLACE PN 6848471 TUBE ASSEMBLIES	1		1	ASB	C20 F, ONLY	NA	NA DUE TO ENGINE MODEL			1-12 2003	A&P2519879			
CO		1321	2			COMPRESSOR - RELEASE OF NEW COMPRESSOR ROTOR ASSY - MODIFY	1		1	2	NEXT OH-REP	X	C.W ON CO SN CAC-35224			22-2 2008	HH. NL.145.1157			
TU		1320					1		1	2	NEXT OH-REP		C.W ON TU SN CAT-37612							
FC	A	1319				FUEL-LUBE-AIR SYSTEM - 23005205 REPLACE HOSE ASSEMBLY	1		1	ASB		NA	NA DUE TO PN AND DATE			28-1 2004	A&P2519879			
TU		1318	1			CHANGE ROUTING OF 1/LEAD TO ELMNT INTERFERENCE	1		1	2	NEXT OH-REP		C.W ON TU SN CAT-37612							
CO		1317				COMPRESSOR- COMPRESSOR CASE, NEW MATERIAL PLASTIC - ADD	1		1	2	NEXT OH-REP	X	C.W ON CO SN CAC-35224			22-2 2008	HH. NL.145.1157			
FC		1316	1			FCU - IMPROVEMENT	1		1	3	NEXT OH-REP		C.W ON FCU SN 323207							
CO		1312				REPLACE COMP. DISCHARGE AIR TUBE PN 23035281	1		1	2	NEXT OH-REP		C.W ON CO SN CAC-35224							
CO		1311	1			ANTHICING VALVE MOD	1		1	2	NEXT OH-REP		C.W ON CO SN CAC-35224							
CO		1308				COMPRESSOR - COMPRESSOR CASE PN 6877410 REPLACE CERTAIN SUSPECT COMPRESSOR CASES	1		1	2	NEXT OH-REP		C.W ON CO SN CAC-35224							
GB		1307				GEARBOX - OIL FILTER TUBE - INSP. OF PN 6876925A FOR PROPER ALIGNMENT	1		1	2	NEXT OH-REP	X	C.W ON GEARBOX SN: CAG-37519			15-4 1993	PHI R.S. HEER617E			
FC		1306				FCU - BENDIX- CONVERSION OF CONFIGURATION	1		1	2	NEXT OH-REP		C.W							
FC	A	1305	1			FCU - BENDIX - VERIFICATION OF MAXIMUM FUEL FLOW SETTINGS	1		1	ASB	AT LOW POWER	NA	NA DUE TO PN, C.W ON FCU SN 323207			28-1 2004	A&P2519879			
BV	A	1304				BLEED VALVE - MOD	1		1	ASB		X	C.W. AT OH ON BV SN FF12055			17-9 2008	ESP-08, BV CC			
CO		1303	3			COMPRESSOR - RELEASE OF NEW COATINGS FOR WHEELS	1		1	3	NEXT OH-REP		C.W ON CO SN CAC-35224							
FC		1302	1			FCU - IMPROVEMENT	1		1	3	NEXT OH-REP		C.W ON FCU SN 323207							
FC		1300				FCU - GOVERNOR - CECO MC40 - REPLACEMENT OF ALL DIAPHRAGMS	1		1	2	NEXT OH-REP		NA DUE TO MODEL							

MANDATORY SERVICE BULLETINES						W:O	CAT		ALERT - MANDATORY	ASB - 1	RECOMMENDED	2	OPTIONAL	3			
A/C REG:		ENG.SN:		EASA TCDS		Page	of		CODE	PCW	PARTIALLY PERFORMED	<input type="checkbox"/>	CANCELLED	<input type="checkbox"/>			
SE-JML		CAE-836554		IM.E.052		"ESB " ROLLS ROYCE 250-C20J		Bi-Weekly 2017-10 EASA		PRE COMPLIED WITH	<input type="checkbox"/>	NOT PERFORMED	<input type="checkbox"/>	PERFORMED	<input checked="" type="checkbox"/>	NOT APPLICABLE	<input type="checkbox"/>
MO	sb	CEB	rev	FAA-AD	EASA AD	ACTION	PART	REP	DUE	CAT	REMARK	CODE	MTD. OF COMPLIANCE	WO NC	DATE	INSP	
TU		1299	2			TURBIN- COMBUSTION LINER REWORK	1		1	2			C.W ON TU SN CAT-37612				
GB		1298	1			GEARBOX - TURBINE PRESSURE OIL FITTING, ADD SEAL	1		1	3	NEXT OH-REP	X	C.W ON GEARBOX SN: CAG-37519		29-6 1999	DALLAS AIRM. YRRR4191L	
FC	A	1295	2			FCU - IMPROVED THROTTLE RETURN SPRING - ADD	1		1	ASB		NA	NA DUE TO PN, C.W ON FCU SN 323207		28-1 2004	A&P2519879	
FC	A	1294	2			COMP-FCU - REPLACE PN 6848471 /23051141 TUBE	1		1	ASB	NEW PN 23054628, PN 23051141	X	C.W INEW TUBE PN INSTALLED		28-1 2004	A&P2519879	
TU	A	1292	1			TURBINE - SPLINE ADAPTER INSP	1		1	ASB	NEXT OH-REP	NA	C.W ON TU SN CAT-37612	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD	
FC		1290				GOVERNOR - AVIALL RECALL OF CERTAIN GOVERNORS	1		1	3	NEXT OH-REP		C.W ON GOV SN 25950				
FC	A	1289				GOVERNOR - PY ACCUMULATOR REMOVE	1		1	ASB		PCW	C.W ON GOV SN 25950		28-1 2004	A&P2519879	
GB		1288	1			GEARBOX - INSTALL NEW PRESSURE OIL TUBE, PN 23053293	1		1	3	NEXT OH-REP	X	C.W ON GEARBOX SN: CAG-37519		18-2 1993	PHI R.S. HEER617E	
BV		1287	2			BLEED VALVE - MOD	1		1	2	NEXT OH-REP	X	C.W. AT OH ON BV SN FF12055		17-9 2008	ESP-08, BV CC	
TU	A	1283	7			TURBIN ASSY, ALSEAL COATING OF POWER TURBINE SHAFTS	1		1	ASB	NEXT OH-REP	X	C.W ON TU SN CAT-37612		HELI-PLAN	2001-05-26	
FC	A	1281	3			GOVERNOR - BENDIX- INSPECT PY PORT CASTING AREA	1		1	ASB	NEXT GOV. OH. A-1289	C.W	NA DUE TO PN, C.W ON GOV SN 25950		28-1 2004	A&P2519879	
TU		1280				TURBINE- NEW GAS PRODUCER TURBINE TIE BOLT SPANNER NUT	1		1	2	NEXT OH-REP		C.W ON TU SN CAT-37612				
TU		1276	3			TURBINE- GP SUPPORT: ADDITIONAL OF BRAZED WEAR PADS	1		1	3			C.W ON TU SN CAT-37612				
GB		1274	3			GEARBOX - INSTL OF NEW 3 AND 4 ROLLER BRGS	1		1	2	NEXT OH-REP	X	C.W ON GEARBOX SN: CAG-37519		7-7 1997	PHI R.S. HEER617E	
TU		1273				TURBINE- INTRNL E-A RING, REWORK FOR SERIES 2 USE	1		1	3			C.W ON TU SN CAT-37612				
FC	A	1272	2	88-17-01		FCU - BENDIX- INSP. OF CERTAIN BENDIX FCU BELLOWS ASSY	1		1	ASB		X	NA BY PN INSTALLED, SN 323207		3-11 1999	A&P454028494	
CO	A	1269				COMPRESSOR - IMPROPER CLAMPING OF THE NO. 1 BRG. PRESSURE OIL TUBE ASSY.	1		1	ASB	C20S	NA	NA DUE TO ENGINE MODEL	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD	
BV		1268				BLEED VALVE - MOD FROM C20S TO C20R SERIES	1		1	2	NEXT OH-REP	X	C.W. AT OH ON BV SN FF12055		17-9 2008	ESP-08, BV CC	
TU		1267				TURBINE- SECOND STAGE TURBINE WHEEL, REDUCED DIAMETER BALANCE PISTON SEAL KNIFE	1		1	3		X	C.W ON TU SN CAT-37612		10-6 2003	ACRA AEROSPACE 231-01 SCA T.11	
GB		1266	1			GEARBOX - CENTRIFUGAL BREATHER GEAR, IMPROVED CONFIGURATION	1		1	3			C.W ON GEARBOX SN: CAG-37519				
EG		1265					1		1	2	NEXT OH-REP		C.W				
FC		1264				C20B TO C2R CONVERSION	1		1	3			NA				
TU		1262	2			TURBINE- FIRST STAGE NOZZLE DIAPHRAM LOCATING KEY WELDS - MODIFY	1		1	3	NEXT OH-REP	X	C.W ON TU SN CAT-37612		10-6 2003	ACRA AEROSPACE 231-01 SCA T.11	

MANDATORY SERVICE BULLETINES										W:O		CAT		ALERT - MANDATORY		ASB - 1		RECOMMENDED		2		OPTIONAL		3	
A/C REG:		ENG.SN:		EASA TCDS		Page		of		CODE		PRE COMPLIED WITH		PCW		PARTIALLY PERFORMED		CANCELLED		NOT APPLICABLE		N			
SE-JML		CAE-836554		IM.E.052		"ESB " ROLLS ROYCE 250-C20J		Bi-Weekly		2017-10 EASA		NOT PERFORMED		PERFORMED		X		NOT APPLICABLE		N		N			
MO	sb	CEB	rev	FAA-AD	EASA AD	ACTION	PART	REP	DUE	CAT	REMARK	CODE	MTD. OF COMPLIANCE	WO NC	DATE	INSP									
FC		1261				FCU- FUEL PUMP- MACHINE PUMP GEAR HOUSING	1		1	3			C.W ON PUMP SN T102440												
CO		1260				ENGINE- AIR SYSTEM, BLEED VALVE, IMPROVED VALVE STEM BUSHING	1		1	3			C.W												
EG		1257	2			ENGINE- SHIPPING CONTAINER - MODIFY	1		1	3			C.W												
TU	A	1255	4	2005-10-13	*	TURBINE - INTERNAL ENERGY ABSORBING RING - ADD	1		1	ASB		X	C.W ON TU SN CAT-37612		28-3 2007	ES PARTNERS AB ESP-2									
TU		1254	3			TURBINE - GAS SUPPORT, MODIFY FOR INCORP. OF AN INTERNAL ENERGY ABSORBING RING	1		1	3	NEXT OH/REP	X	C.W ON TU SN CAT-37612		28-3 2007	ES PARTNERS AB ESP-2									
TU		1253	4			TURBINE - FIRST -SECOND STAGE TURBINE NOZZLES, - MODIFY	1		1	3		X	C.W ON TU SN CAT-37612		28-3 2007	ES PARTNERS AB ESP-2									
FC		1252				FCU - CECO- REPLACE LAMINATED SHIMS WITH SOLID SHIMS	1		1	3			NA THIS INSTALLATION DUE TO PN												
TU		1251					1		1	2			C.W ON TU SN CAT-37612												
FC		1245	2			FCU - IMPROVEMENT	1		1	3			C.W ON FCU SN 323207												
FC		1244				FCU- GOVERNOR - INCREASED PRESSURE BENCH CALIBRATION	1		1	3			C.W ON GOV SN 25950												
CO		1242				ENGINE COMP - CONVERSION 250-C20B TO C20R	1		1	3			C.W ON CO SN CAC-35224												
GB		1241	1			GEARBOX -OIL FILTER HOUSING, ADD BRONZE BUSHING	1		1	3	NEXT OH-REP	PCW	C.W ON GEARBOX SN: CAG-37519		7-12 1994	PHI RS#HEFR617E									
TU		1239	1			TURBINE ASSY "U" RING GASKET REPLACE	1		1	2		X	C.W ON TU SN CAT-37612		1-9 1988	ELIGOTTERI ITALIA									
CO	A	1234	3			COMPRESSOR - PC SCROLL TO PC FILTER TUBE ASSY INSP	1	1	1	ASB	NEW PN 23054628, PN 23051141		C.W INSP EACH TIME WHEN TUBE IS REMOVED												
CO	A	1233	2			AIR SYSTEM- IMPROVED STRENGHT PC FILTER HOUSING, REPLACE PN 6875726, AND 6874958	1		1	ASB	NEW HOUSING PN 23034711, 23033400	PCW	C.W INSTALLED PN 23033400	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD									
GB		1228				GEARBOX: NEW ACCESSORY DRIVE SYSTEM BEARING	1		1	3		X	C.W ON GEARBOX SN: CAG-37519		29-9 1986	PHI 863018									
GB	A	1226	4			GEARBOX - ACCESSORY GEARBOX ASSEMBLY, THROUGH BOLT RETENTION OF IDLER GEARS	1		1	ASB		X	C.W ON GEARBOX SN: CAG-37519		7-12 1994	PHI RS#HEFR617E									
GB		1225	2			ENGINE OR MODULE CONVERSION AUTHORIZATION	1		1	3			C.W ON GEARBOX SN: CAG-37519												
TU	A	1224	2			TURBINE - INNER AND OUTER POWER TURBINE SHAFT THICKER ELECTROLESS NICKEL PLATE	1		1	ASB	CEB-1176	X	C.W ON TU SN CAT-37612		1-9 1988	ELIGOTTERI ITALIA									
TU		1223	1			TURBINE - POWER TURBINE INNER AND OUTER SHAFTS-ELECTROLESS NICKEL PLATING	1		1	2		X	C.W ON TU SN CAT-37612		1-9 1988	ELIGOTTERI ITALIA									
TU		1221	5			TURBINE - POWER TURBINE SUPPORT, OIL SUMP COVER ASSY. - MODIFY	1		1	2			C.W ON TU SN CAT-37612												
GB		1218				GEARBOX - SCAVENGER. OIL PUMP COVER ASSY -ADD LOCTITE TO GEAR SHAFTS	1		1	3		X	C.W ON GEARBOX SN: CAG-37519		10-3 1999	DALLAS AIRM. YRRR4191L									
FC		1214	2			ENGINE - FCU AND GOVERNOR ASSEMBLY - MODIFY	1		1	3		X	C.W		29-6 1999	DALLAS AIRM. YRRR4191L									

MANDATORY SERVICE BULLETINES						W:O	CAT		ALERT - MANDATORY		ASB - 1	RECOMMENDED	2	OPTIONAL	3	
A/C REG:		ENG.SN:		EASA TCDS		Page	of		CODE		PCW	PARTIALLY PERFORMED	CANCELLED			
SE-JML		CAE-836554		IM.E.052		"ESB " ROLLS ROYCE 250-C20J		Bi-Weekly		2017-10 EASA		NOT PERFORMED	PERFORMED	NOT APPLICABLE		
MO	sb	CEB	rev	FAA-AD	EASA AD	ACTION	PART	REP	DUE	CAT	REMARK	CODE	MTD. OF COMPLIANCE	WO NC	DATE	INSP
BV		1213				AIR SYSTEM- COMPRESSOR BLEED VALVE ASSEMBLY - MODIFY	1		1	3		X	C.W. AT OH ON BV SN FF12055		17-9 2008	ESP-08, BV CC
TU		1212	3			TURBINE - GAS PRODUCER ROTOR TIE BOLT	1		1	2		X	C.W ON TU SN CAT-37612		1-9 1988	ELIGOTTERI ITALIA
GB	A	1211	3			GEARBOX - QUICK DISCONNECT MAG PLUG	1		1	ASB	100 HRS INSP	X	C.W ON GEARBOX SN: CAG-37519, INCORP IN MP206B CHAP 4.1	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD
FC		1207	2			FCU - GOV IMPROVEMENT	1		1	3			C.W ON GOV SN 25950			
FC	A	1206		82-24-05		FCU- GOVERNOR CHECK/ EXCH. OF BRG NYLON HOLDER	1		1	ASB		X	C.W		29-6 1999	DALLAS AIRM. YRRR4191L
TU		1204	1			TURBINE - RETAINING RING 6 & 7 BEARINGS - INSPECTED	1		1	2			C.W ON TU SN CAT-37612			
CO		1203				COMPRESSOR - INSPECTION OF THE 6 TH STAGE COMPRESSOR WHEEL	1		1	2	NEXT OH-REP		C.W ON CO SN CAC-35224			
GB		1201	2			GEARBOX - INSPECT MARLIN-ROCKWELL BEARINGS	1		1	3		X	C.W ON GEARBOX SN: CAG-37519		10-3 1999	DALLAS AIRM. YRRR4191L
FC		1200				GOVERNOR- BENDIX- INCORPORATION OF GOVERNOR BODY ACCESS WINDOW	1		1	3			C.W ON GOV SN 25950			
GB		1199	1			GEARBOX - OIL PUMP ATTACH BOLTS	1		1	3		X	C.W ON GEARBOX SN: CAG-37519		2-8 1985	PHI 852483
FC		1198	2			FCU - GOVERNOR -PR PRESSURE TUBE TO FCU-ADD TWO CLAMPS	1		1	1		PCW	P.C.W CLAMPS INSTALLED	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD
TU		1197				GAS PRODUCER ROTOR ASSEMBLY-REPLACE TIE BOLT	1		1	2	NEXT OH-REP		C.W ON TU SN CAT-37612			
FC	A	1194				FUEL PUMP - SUNDSTRAND SINGLE ELEMENT INSPECT DRIVE SHAFT	1		1	ASB	SUNDSTRAND	NA	NA THIS INSTALLATION DUE TO PN		1-12 2003	A&P2519879
GB		1192				GEARBOX - POWER TAKEOFF GEAR SHAFT RETAINING RING - ADD	1		1	3			C.W ON GEARBOX SN: CAG-37519			
EG		1191				ENGINE - C20 J CONVERT TO- C20F ENG. ENG GB	1		1	2		NA	NA DUE TO ENGINE MODEL		30-3 1993	PHI R.S. HEER617E
EG		1190	1			ENGINE - CONVERSION C20F TO- C20J, ENG GB	1		1	2			NA DUE TO ENGINE MODEL			
EG		1189				ENGINE - C20 J CONVERT TO- C20B ENG.	1		1	2			C.W			
EG		1188				ENGINE - GB CONVERSION C20B TO- C20J	1		1	2		X	C.W		29-6 1999	DALLAS AIRM. YRRR4191L
TU		1185				G.P- P.T- SUPPORT AND SEAL ASSY - BREAK EDGE	1		1	3		X	C.W ON TU SN CAT-37612		10-6 2003	ACRA AEROSPACE 231-01 SCA T. 11
TU		1183	1			GP. TURBINE SUPT ASSEMBLY-ANTI-ROTATION PIN REPLACE	1		1	3		X	C.W ON TU SN CAT-37612		28-3 2007	ES PARTNERS AB ESP-2
TU		1181				TURBINE - ASSEMBLY, MODIFY C20F FOR SERIES II COMMONALITY	1		1	3			C.W			
TU		1178	2			TURBINE - PT INNER AND SHAFTS INCREASED DIAMETER	1		1	3			C.W ON TU SN CAT-37612			
GB		1177	1			GEARBOX - INSPECT OIL DELIVERY TUBE (PICCOLO) FOR BURRS	1		1	3		X	C.W ON GEARBOX SN: CAG-37519		2-8 1985	PHI 852483

MANDATORY SERVICE BULLETINES						W:O	CAT		ALERT - MANDATORY		ASB - 1	RECOMMENDED	2	OPTIONAL	3		
A/C REG:		ENG.SN:		EASA TCDS		Page	of		CODE		PCW	PARTIALLY PERFORMED	<input type="checkbox"/>	CANCELLED		<input type="checkbox"/>	
SE-JML		CAE-836554		IM.E.052		"ESB " ROLLS ROYCE 250-C20J		Bi-Weekly		2017-10 EASA		NOT PERFORMED	<input type="checkbox"/>	PERFORMED	<input checked="" type="checkbox"/>	NOT APPLICABLE	<input type="checkbox"/>
MO	sb	CEB	rev	FAA-AD	EASA AD	ACTION	PART	REP	DUE	CAT	REMARK	CODE	MTD. OF COMPLIANCE		WO NC	DATE	INSP
TU		1176	1			TURBINE PT INNER AND OUTER SHAFTS AND INNER COUPLING NUT- ELECTROLESS PLATED	1		1	3	NEXT OH-REP		C.W ON TU SN CAT-37612				
TU	A	1174	6	83-03-02R1		TURBINE - 3rd WHEEL EXCHANGE/ DECAL INSTALLATION	1		1	ASB	TURBINE OVERTEMP	X	C.W AT FACTORY BEFORE DELIVERY			19-12 1990	AGT-GMC
TU	A	1173				TURBINE INNER AND OUTER PT. SHAFTS REPLACE	1		1	3	NEXT OH-REP		C.W ON TU SN CAT-37612				
EG		1172				REPLACE DOME ASSY FOR SERVICE REPAIR	1		1	2			C.W				
CO		1171	2			COMPRESSOR - NO.1 BRG. RETAINING NUT REPLACE	1		1	2	NEXT OH-REP		C.W ON CO SN CAC-35224				
FC	A	1170	4			GOVERNOR- BENDIX- INSPECT DRIVE SHAFT AND ADD EPOXY BONDING TO TORSIONAL SPRING DRIVE ASSEMBLY	1		1	3		X	C.W			29-6 1999	DALLAS AIRM. YRRR4191L
GB		1168	3			GEARBOX COVER ASSY-REPLACE PINION BEARING CAGE	1		1	3		PCW	C.W ON GEARBOX SN: CAG-37519			5-6 1990	PHI R.S. HEER617E
TU		1167	2			TURBINE: TURBINE CONVERSION FROM C20B TO C20	1		1	3			C.W ON TU SN CAT-37612				
GB		1166	2			GEARBOX - HOUSING AND COVER-HELICAL COIL INSERTS	1		1	3		X	C.W ON GEARBOX SN: CAG-37519			2-8 1985	PHI 852483
GB		1165	3			GEARBOX - SPACE ACCESSORY DRIVE-REMOVE	1		1	3		PCW	C.W ON GEARBOX SN: CAG-37519			7-12 1994	PHI RS#HEFR617E
FC		1164				SUNDSTRAND FUEL PUMP AND FILTER ASSEMBLY	1		1	3			C.W				
FC		1163	1			FCU- GOVERNOR- CECO- BELLOWS ASSY - REPLACE	1		1	3		NA	NA DUE TO BENDIX INSTL			28-1 2004	AP 2519879
FC		1162	1			FCU - GOV IMPROVEMENT	1		1	3			C.W				
TU		1161	2			TURBINE - 6 & 7 BEARING PRESSURE OIL NOZZLE- REPLACE	1		1	3		X	C.W ON TU SN CAT-37612			14-6 1985	AVIALL
TU		1158	3			TURBINE - POWER TURBINE OUTER COUPLING NUT-REWORK	1		1	3		X	C.W ON TU SN CAT-37612			13-2 1986	AVIALL
GB		1157				GEARBOX - POWER AND ACCESSORY PTO GEAR SHAFT GROOVES	1		1	3		X	C.W ON GEARBOX SN: CAG-37519			29-3 1994	AGT-GMC
CO		1156				BLEED VALVE- GASKET- REPLACE	1		1	2	AT COMP EXCH		C.W				
TU		1155	1			TURBINE - TURBINE SUPPORT AND SEAL ASSY. EXTEND INNER CROSS SECTION OF SCAVENGE OIL DRAIN STRUT	1		1	2		X	C.W ON TU SN CAT-37612			29-3 1994	AGT-GMC
GB		1154	6			GEARBOX - OIL FILTER DIFFERENTIAL PRESSURE INDICATOR	1		1	3		X	C.W ON GEARBOX SN: CAG-37519			29-3 1994	AGT-GMC
GB		1150	7			GEARBOX ASSY P.T.O HELICAL GEARSHAFT	1		1	2	NEXT OH-REP	PCW	C.W ON GEARBOX SN: CAG-37519			18-1 1988	PHI 873348
TU		1149				TURBINE - REWORK 3RD STAGE NOZZLE	1		1	2		X	C.W ON TU SN CAT-37612			29-3 1994	AGT-GMC
TU		1148		79-21-01R1		TURBINE - 3rd TURBINE WHEEL EXCHANGE	1		1	ASB		X	C.W AT FACTORY BEFORE DELIVERY			29-3 1994	AGT-GMC
GB		1147	6			GEARBOX - COVER HOUSING SELF LOCKING THREADED INSERTS- ADD	1		1	2	NEXT OH-REP	PCW	C.W ON GEARBOX SN: CAG-37519			18-1 1988	PHI 873348

MANDATORY SERVICE BULLETINES						W:O	CAT		ALERT - MANDATORY		ASB - 1	RECOMMENDED	2	OPTIONAL	3		
A/C REG:		ENG.SN:		EASA TCDS		Page	of		CODE		PCW	PARTIALLY PERFORMED	<input type="checkbox"/>	CANCELLED		<input type="checkbox"/>	
SE-JML		CAE-836554		IM.E.052		"ESB " ROLLS ROYCE 250-C20J		Bi-Weekly		2017-10 EASA		NOT PERFORMED	<input type="checkbox"/>	PERFORMED	<input checked="" type="checkbox"/>	NOT APPLICABLE	<input type="checkbox"/>
MO	sb	CEB	rev	FAA-AD	EASA AD	ACTION	PART	REP	DUE	CAT	REMARK	CODE	MTD. OF COMPLIANCE	WO NC	DATE	INSP	
FC		1146				FCU - SCHEDULE ADJUSTER - ADD	1		1	2		X	C.W ON FCU SN 323207		29-3 1994	AGT-GMC	
FC		1145				FUEL PUMP- TRW- FIXED AND PRESSURIZED BEARINGS - REWORK	1		1	2		X	C.W ON PUMP SN T102440		29-3 1994	AGT-GMC	
FC	A	1144	5	82-13-03		CECO FUEL CONTROL MC-40 SYSTEM MODIFY HIGH PRESSURE FILTER UNIT	1		1	ASB	PN 6875653	NA	NA BENDIX INSTALLED		1-12 2003	A&P2519879	
GB		1143	8			GEARBOX - QUICK DISCONNECT MAG PLUG	1		1	2	NEXT OH-REP	X	C.W ON GEARBOX SN: CAG-37519		9-11 2001	SAL-AMO-22-58	
TU		1142	2			TURBINE - POWER TURBINE SHAFT SHIELD - REPLACE	1		1	2		X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
GB		1141	2			GEARBOX- POWER AND ACCESORAY POWER TRAIN DRIVE GEAR BEARING JOURNALS - MODIFY	1		1	2	NEXT OH-REP	PCW	C.W ON GEARBOX SN: CAG-37519		5-6 1990	PHI R.S. HEER617E	
BV		1140				BLEED VALVE - PISTON AND RETAINER - REPLACE	1		1	2	NEXT OH-REP	X	C.W AT FACTORY BEFORE DELIVERY		29-3 1994	AGT-GMC	
CO		1139	1			COMPRESSOR- NO. 1BEARING OIL PRESSURE REDUCER - REPLACE	1		1	2	NEXT OH-REP	X	C.W ON CO SN CAC-35224		29-3 1994	AGT-GMC	
FC		1138	2			FCU - GOVENOR : SCREEN ORFICE REPLACE	1		1	3	NEXT OH-REP	X	C.W		29-3 1994	AGT-GMC	
TU		1136	1			TURBINE- SECOND STAGE TURBINE WHEEL AND SPLINED ADAPTOR - REPLACE	1		1	2		X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
TU		1135	1			TURBINE - REPLACE VERTICAL FIREWALL ASSY	1		1	2		X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
GB		1132				GEARBOX, OIL CHECK VALVE, REPLACE	1		1	2	NEXT OH-REP	X	C.W ON GEARBOX SN: CAG-37519		29-3 1994	AGT-GMC	
GB		1131				GEARBOX- POWER ACCESORAY OIL FILTER CAP- REPLACE	1		1	2	NEXT OH-REP	X	C.W ON GEARBOX SN: CAG-37519		29-3 1994	AGT-GMC	
FC		1130				GOVERNOR- BENDIX- DRIVE SPLINE COUPLING- REPLACE	1		1	2		X	NA BY PN ON GOV SN 25950		29-3 1994	AGT-GMC	
CO		1129				BLEED VALVE - PN 6875120/ 6889815 INSTAL FILTER ASSY	1		1	ASB	NEXT OH-REP	NA	NA DUE TO PN, C.W ON CO SN CAC-35224		29-3 1994	AGT-GMC	
TU		1128	1			TURBINE- NO. 5 OIL BELLOWS SEAL ASSY. - REPLACE	1		1	2	NEXT OH-REP	X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
TU		1127	4			TURBINE - PT ROTOR - MODIFY REF CEB 1174	1		1	2	NEXT TURBINE OH	X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
FC		1125				GOVERNOR - THROTTLE SHAFT TO SN 18156 INSPECT	1		1	2	C20 ONLY	NA	NA ON GOV SN 25950		29-3 1994	AGT-GMC	
TU		1124	1			TURBINE - GAS PRODUCER FWD LABYRINTH SEAL - REPLACE	1		1	2	NEXT TURBINE OH	X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
GB		1122	4			GEARBOX- HOUSING AND COVER OIL PRESSURE PORTS HELICAL COIL INSERTS	1		1	2	NEXT OH-REP	X	C.W ON GEARBOX SN: CAG-37519		2-8 1985	PHI 852483	
TU		1120	2	77-15-12		TURBINE - POWER TURBIN COUPLING NUT - REPLACE	1		1	ASB	CSL-1060	X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
GB		1118	2			GEARBOX- REWORK FCU & OIL PUMP SPUR GEARSHAFT	1		1	2	NEXT OH-REP	NA	C.W ON GEARBOX SN: CAG-37519		7-7 1989	PHI RS#HEFR617E	
FC		1117				FUEL PUMP- TRW- MAIN DRIVE SHAFT SPACER- ADD	1		1	2		X	C.W ON PUMP SN T103296		29-3 1994	AGT-GMC	

MANDATORY SERVICE BULLETINES						W:O			CAT		ALERT - MANDATORY ASB - 1		RECOMMENDED 2	OPTIONAL 3			
A/C REG:		ENG.SN:		EASA TCDS		Page		of		CODE		PRE COMPLIED WITH PCW		PARTIALLY PERFORMED <input type="checkbox"/>		CANCELLED <input type="checkbox"/>	
SE-JML		CAE-836554		IM.E.052		"ESB " ROLLS ROYCE 250-C20J		Bi-Weekly 2017-10 EASA		NOT PERFORMED <input type="checkbox"/>		PERFORMED <input checked="" type="checkbox"/>		NOT APPLICABLE <input type="checkbox"/>		N	
MO	sb	CEB	rev	FAA-AD	EASA AD	ACTION	PART	REP	DUE	CAT	REMARK	CODE	MTD. OF COMPLIANCE	WO NC	DATE	INSP	
BV		1116	2	77-09-08		BLEED VALVE - PN 6875120/ 6889815 INSTAL FILTER ASSY	1		1	ASB	BLEED VALVE	X	C.W AT FACTORY BEFORE DELIVERY		29-3 1994	AGT-GMC	
CO		1115				ANTI-ICING VALVE POPPET SEAT SCREW - SPECIAL INSPECTION	1		1	2	NEXT OH-REP	X	C.W ON CO SN CAC-35224		29-3 1994	AGT-GMC	
TU		1114		77-18-03		TURBINE - 3rd TURBINE WHEEL EXCHANGE/ DECAL INSTALLATION	1		1	ASB	TURBINE OVERTEMP	X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
FC		1111				FCU - BENDIX-RATIO LEVER ASSY. - REPLACE	1		1	2		X	C.W ON FCU SN 323207		29-3 1994	AGT-GMC	
CO		1110				COMPRESSOR - CONVERSION TO C20B CONFIGURATION	1		1	2	NEXT OH-REP	X	C.W ON CO SN CAC-35224		29-3 1994	AGT-GMC	
FC		1109				FCU - GOVERNOR- BENDIX- SPRING-REPLACE	1		1	2		X	C.W ON FCU SN 323207		29-3 1994	AGT-GMC	
BV		1107				BLEED VALVE - MOD	1		1	2	NEXT OH-REP	X	C.W AT FACTORY BEFORE DELIVERY		29-3 1994	AGT-GMC	
FC		1106	1			GOVERNOR - THROTTLE SHAFT TO SN 18156 INSPECT	1		1	2		X	NA BY PN ON GOV SN 25950		29-3 1994	AGT-GMC	
GB		1105	4			GEARBOX- POWER AND ACCESORAY COVER ASSY. TORQUEMETER SHAFT BORE BUSHING-ADD	1		1	3		NA	C.W ON GEARBOX SN: CAG-37519		7-12 1994	PHI RS#HEFR617E	
FC		1103				FCU - BENDIX- ENRICHED ACCELARATION FLOW SHCHEDULE- INCORPORATE	1		1	2		X	C.W ON FCU SN 323207		29-3 1994	AGT-GMC	
FC		1101	1			ADD FUEL CHECK VALVE ASSY	1		1	2	NEXT OH-REP	X	C.W		29-3 1994	AGT-GMC	
CO		1100				COMPRESSOR - FRONT BEARING HOUSING ASSY-REWORK	1		1	2	NEXT OH-REP	X	C.W ON CO SN CAC-35224		29-3 1994	AGT-GMC	
TU		1099				TURBINE - P.T AND SEAL ASSY	1		1	2	NEXT OH-REP	X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
GB		1098	4			GEARBOX- LUBE OIL FILTER HOUSING AND PRESSURE OIL PUMP BODY- REWORK	1		1	2	NEXT OH-REP	NA	C.W ON GEARBOX SN: CAG-37519		7-12 1994	PHI R.S. HEER617E	
FC	A	1095	3			INSTALL HP FILTER INSTALLATION	1		1	ASB	CECO ONLY	NA	NA DUE TO BENDIX INSTL		1-12 2003	A&P2519879	
TU		1094				REWORK EXHAUST COLLECTOR SUPPORT	1		1	2		X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
TU		1091				TURBINE - REWORK 8 BRG RTNNG PLATE & GP SUPPORT	1		1	2		X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
FC		1090	2			GOVERNOR - MOD TO PN2524706-1	1		1	2		X	NA BY PN ON GOV SN 25950		29-3 1994	AGT-GMC	
FC		1089				FCU - BENDIX- FUEL INLET FILTER ASSEMBLY- REPLACE	1		1	2		X	C.W ON FCU SN 323207		29-3 1994	AGT-GMC	
CO		1088				COMPRESSOR - REAR DIFFUSOR ASSEMBLY	1		1	2	NEXT OH-REP	X	C.W ON CO SN CAC-35224		29-3 1994	AGT-GMC	
GB		1087				GEARBOX- OIL PUMP COVER - REWORK	1		1	2	NEXT OH-REP	NA	C.W ON GEARBOX SN: CAG-37519		7-7 1989	PHI RS#HEFR617E	
FC		1086	2			GOVERNOR- BENDIX- THROTTLE STOP LEVER TRAVEL - INCREASE	1		1	2		X	NA BY PN ON GOV SN 25950		29-3 1994	AGT-GMC	
EG		1085				REPLACE NO 1 BRG & ANTI ICE TUBE CLAMPS	1		1	2	NEXT OH-REP	X	C.W		29-3 1994	AGT-GMC	

MANDATORY SERVICE BULLETINES						W:O			CAT		ALERT - MANDATORY ASB - 1		RECOMMENDED 2	OPTIONAL 3			
A/C REG:		ENG.SN:		EASA TCDS		Page		of		CODE		PRE COMPLIED WITH PCW		PARTIALLY PERFORMED <input type="checkbox"/>		CANCELLED <input type="checkbox"/>	
SE-JML		CAE-836554		IM.E.052		"ESB " ROLLS ROYCE 250-C20J		Bi-Weekly 2017-10 EASA		NOT PERFORMED <input type="checkbox"/>		PERFORMED <input checked="" type="checkbox"/>		NOT APPLICABLE <input type="checkbox"/>		N	
MO	sb	CEB	rev	FAA-AD	EASA AD	ACTION	PART	REP	DUE	CAT	REMARK	CODE	MTD. OF COMPLIANCE	WO NC	DATE	INSP	
GB		1082	4			STARTER- GEN- WET SPLIN STARTER GEN GEARSHAFT - INSTALL	1		1	2	NEXT OH-REP	X	C.W ON GEARBOX SN: CAG-37519		29-3 1994	AGT-GMC	
FC		1081	1			INSTALL NEW PN BENDIX PTG FOR B0105C&D	1		1	3		X	NA		29-3 1994	AGT-GMC	
FC		1080	1			GOVERNOR- BENDIX- DRIVE BODY COVER THROTTLE SHAFT BUSHING - REPLACE	1		1	2		X	NA BY PN ON GOV SN 25950		29-3 1994	AGT-GMC	
FC		1079				FCU - BENDIX- MAIN BODY THROTTLE SHAFT BUSHING -REPLACE	1		1	2		X	C.W ON FCU SN 323207		29-3 1994	AGT-GMC	
TU		1078				TURBINE- FIRST STAGE NOZZLE SHIELD ASSY. - REWORK	1		1	2		X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
FC		1077				GOVERNOR - BENDIX - MODEL AL-AAI- MOD. TO PARTS LIST NO: 2524667-2	1		1	2		X	NA BY PN ON GOV SN 25950		29-3 1994	AGT-GMC	
CO		1076				COMPRESSOR - SPUR ADAPTER GEARSHAFT BRG INNER RACE	1		1	2	NEXT OH-REP	X	C.W ON CO SN CAC-35224		29-3 1994	AGT-GMC	
CO		1074				COMPRESSOR - NO. 1 BRG. RELIEVED OUTER RACE	1		1	2	NEXT OH-REP	X	C.W ON CO SN CAC-35224		29-3 1994	AGT-GMC	
GB		1073				GEARBOX - REPLACE OIL FILTER INLET TUBE ASSY	1		1	2	NEXT OH-REP	X	C.W ON GEARBOX SN: CAG-37519		29-3 1994	AGT-GMC	
CO		1072				COMPRESSOR - NO. 1 BRG. IMPROVED SEAL	1		1	2	NEXT OH-REP	X	C.W ON CO SN CAC-35224		29-3 1994	AGT-GMC	
CO		1071				COMPRESSOR - NEW FRONT SUPPORT	1		1	2	NEXT OH-REP	X	C.W ON CO SN CAC-35224		29-3 1994	AGT-GMC	
FC		1067				FUEL NOZZLE - V-SLOT MEETERING VALVE INSTALL AND REIDENTIFY	1		1	2		X	C.W ON NOZZLE AG16457		29-3 1994	AGT-GMC	
EG		1065	2			REPLACE IGNITER LEAD CLAMPS	1		1	4		X	C.W		29-3 1994	AGT-GMC	
EG		1064					1		1	2		X	C.W		29-3 1994	AGT-GMC	
TU		1062				REPLACE TURBINE SPLITLINE BOLT	1		1	2		X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
BV		1061				BLEED VALVE ASSEMBLY - REWORK	1		1	2	NEXT OH-REP	X	C.W AT FACTORY BEFORE DELIVERY		29-3 1994	AGT-GMC	
GB		1060				GEARBOX- NO 2 1/2 ROLLER BRG. ASSY. - REPLACE	1		1	2	NEXT OH-REP	X	C.W ON GEARBOX SN: CAG-37519		29-3 1994	AGT-GMC	
EG		1056					1		1	2		X	C.W		29-3 1994	AGT-GMC	
TU		1054				TURBINE - STG 2 NOZZLE MODIFY TO C20B CONFIGURATION	1		1	2	NEXT OH-REP	X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC	
EG		1053	3			ENGINE MODEL 250-C20 SERIES CONVERSION TO- C20B	1		1	2	NEXT OH-REP	PCW	C.W AT FACTORY BEFORE DELIVERY		7-12 1994	PHI RS#HEFR617E	
FC		1051	1	78-14-08		FUEL PUMP - INSP. SPLINE GEAR	1		1	ASB	200 HRS INSP	X	C.W AT FACTORY BEFORE DELIVERY		29-3 1994	AGT-GMC	
EG		1050				FUEL SYSTEM CONVERSION - CECO TO BENDIX	1		1	2		X	C.W		29-3 1994	AGT-GMC	
GB		1049	2			GEARBOX - REWORK LUBE OIL FILTER HSG ASSY	1		1	2	NEXT OH-REP	X	C.W ON GEARBOX SN: CAG-37519		29-3 1994	AGT-GMC	

MANDATORY SERVICE BULLETINES						W:O			CAT	ALERT - MANDATORY ASB - 1 RECOMMENDED 2 OPTIONAL 3						
A/C REG:		ENG.SN:		EASA TCDS		Page of		CODE	PRE COMPLIED WITH PCW PARTIALLY PERFORMED		CANCELLED					
SE-JML		CAE-836554		IM.E.052		"ESB " ROLLS ROYCE 250-C20J		Bi-Weekly 2017-10 EASA		NOT PERFORMED PERFORMED		NOT APPLICABLE N				
MO	sb	CEB	rev	FAA-AD	EASA AD	ACTION	PART	REP	DUE	CAT	REMARK	CODE	MTD. OF COMPLIANCE	WO NC	DATE	INSP
EG		1048					1		1	2		X	C.W		29-3 1994	AGT-GMC
GB		1046	2			GEARBOX - TORQUE METER SHAFT, REAR NUT CONFIGURATION	1		1	2	NEXT OH-REP	NA	C.W ON GEARBOX SN: CAG-37519		7-12 1994	PHI RS#HEFR617E
TU		1045				TURBINE - FOURTH STAGETURBINE NOZZLE- REWORK	1		1	2	NEXT OH-REP	X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC
EG		1042	1			REPLACE F/P FCU & FCU F/P TUBES CLAMPS	1		1	2		X	C.W		29-3 1994	AGT-GMC
FC		1040	2	73-19-07		CLAMPING OF FCU TUBES	1		1	ASB		X	C.W AT FACTORY BEFORE DELIVERY		29-3 1994	AGT-GMC
GB		1039				COVER ASSY BOSSES REWORK	1		1	2		NA	C.W ON GEARBOX SN: CAG-37519		7-7 1989	PHI RS#HEFR617E
GB		1014	1				1		1	2		NA	C.W ON GEARBOX SN: CAG-37519		7-7 1989	PHI RS#HEFR617E
GB		1013	3			GEARBOX - MOUNTING INSERTS	1		1	2	NEXT OH-REP	NA	C.W ON GEARBOX SN: CAG-37519		7-12 1994	PHI RS#HEFR617E
GB		1010	1				1		1	2		NA	C.W ON GEARBOX SN: CAG-37519		7-7 1989	PHI RS#HEFR617E
EG		1006					1		1	2	NEXT OH-REP	X	C.W AT FACTORY BEFORE DELIVERY		29-3 1994	AGT-GMC
EG		1003					1		1	2		X	C.W AT FACTORY BEFORE DELIVERY		29-3 1994	AGT-GMC
EG		1002					1		1	2		X	C.W AT FACTORY BEFORE DELIVERY		29-3 1994	AGT-GMC
GB		1001	2				1		1	2		NA	C.W ON GEARBOX SN: CAG-37519		18-2 1993	PHI RS#HEFR617E
TU				96-19-01		TURBIN BEARING NO 5 AND 8, INSTALLED MFG BY SUPERIOR AIR PARTS, REPLACE	1		1	ASB	C.W, NON SUPERIOR PARTS INSTL AT MCI	X	C.W ON TU SN CAT-37612		HELI-PLAN	37037
EG				93-25-05		SOLOY CONVERSION ENGINE C20S - MAIN ENGINE DRIVESHAFT	1		1	ASB	STC SE2352NM, C20S	NA	NA, DUE TO ENGINE MODEL, INSTL		1-12 2003	A&P2519879
FC				04-24-04		FCU/HMU	1		1	1	C30 only	NA	NA BY MODELL		15-2 2005	SE.145.0065
TU				2015-02-22	*	3rd AND 4th STAGE TURBINE WHEEL BLADES - INSPECTION; PN: 23055944 & 23065818	1		1	ASB	SS 2012-14-06	NA	NA DUE TO PN WHEELS INSTALLED	HNAB CAMO	22-5 2017	SE.MG.0092-3 LGD
TU				72-03-06		SECOND STAGE TURBINE WHEELS	1		1	ASB		X	C.W ON TU SN CAT-37612		29-3 1994	AGT-GMC